



## **ENGINE FOR SALE**

<b>Model</b>	PT6T-3DF	<b>Serial Number</b>	CP-PS TH0709
<b>TSN</b>	9,438.8	<b>TSO</b>	0.0

<b>Component</b>	<b>Part Number</b>	<b>Serial Number</b>	<b>T/C</b>	<b>Life Limit</b>	<b>CSN</b>	<b>TCR</b>
Hub	3041255	A001MTMW	Cycles	35,000	23,615	11,385
2nd Stage Disk	3040312	A00379D5	Cycles	29,000	13,196	15,804
3rd Stage Disk	3040213	A0037EP0	Cycles	29,000	13,196	15,804
Impeller	3027798	4E605	Cycles	29,000	13,929	15,071
CT Disk	3041241	TBD	Cycles	7,200	0	7,200
PT Disk	3045622	A002CM21	Cycles	15,000	6,266	8,734

<b>Component</b>	<b>Part Number</b>	<b>Serial Number</b>	<b>TSN</b>	<b>TSO</b>	<b>Remaining TBO</b>	
AFCU	3244883	TBD	Unknown	0.0	<b>NA</b>	<b>FULL TBO</b>
MFCU	3244884	TBD	Unknown	0.0	<b>NA</b>	<b>FULL TBO</b>
Fuel Pump	025277-300	TBD	Unknown	0.0	<b>NA</b>	<b>FULL TBO</b>
Oil/Fuel Heater	10544	TBD	Unknown	0.0	<b>NA</b>	<b>FULL TBO</b>
Flow Divider	3120483-01	TBD	Unknown	0.0	<b>NA</b>	<b>FULL TBO</b>
Bleed Valve	540-1407-4	TBD	40.5	NA	<b>NA</b>	<b>OC</b>
Trim Compensator	Not Installed	NA	NA	NA	<b>NA</b>	<b>NA</b>
Ignition Exciter	Not Installed	NA	NA	NA	<b>NA</b>	<b>NA</b>

**Consolidated Turbine Specialists, LLC**

24323 South 385th West Avenue, PO Box 596

Bristow, OK 74010

918-367-9665

[www.ctsturbines.com](http://www.ctsturbines.com)